Montageanleitung/Mounting instructions

Contec CV- und CE- Verbinder nach DIN 19522 / EN 877
Contec CV- and CE- Coupling as per DIN 19522/EN 877

Contec
SML-Verbindungstechnik GmbH

1.

2.

3.

4.


5.

Anzugsdrehmomente Tightening torque approx	
DN 50 - DN 70	ca. 6 Nm
DN 100 - DN 150	ca. 8 Nm

Montage:

1. Manschette auf das Rohrende stecken. Mittlerer Distanzring der Dichtung liegt auf dem Rohr auf.
2. Überstehendes Teil der Manschette nach unten umklappen.
3. Nächstes Rohr- bzw. Formstück bündig auf den Distanzring der Manschette aufsetzen.
4. Manschette zurückklappen.
5. Verbinder aufsetzen und mit Schraubwerkzeug wechselseitig, gleichmäßig festziehen.

Mounting:

1. Place the collar on the end of the pipe. The centre spacer ring with seal will rest on the pipe.
2. Fold down the projecting part.
3. Place the next pipe or fitting flush on the spacer ring of the collar.
4. Fold back the collar.
5. Place the connector on and use a screwdriver to tighten it alternately and uniformly.

Contec SML-Verbindungstechnik GmbH
Eisenhüttenstraße 17 - 19
D-57074 Siegen

Telefon 0271/66 11 50
Telefax 0271/66 11 555
Email: info@contec-sml.de

Stand: 06/2016